

HABS
ORE
15-MED,
1E-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Medford Service Center, Gas-and-Oil House (Building #2500) HABS No. OR-160-E
1319 McAndrews Road
Medford
Jackson County
Oregon

Natalie Brown, Photographer

April 1993

- OR-160-E-1 VIEW OF EAST SIDE AND NORTH REAR OF GAS-AND-OIL HOUSE (BUILDING #2500), FACING SOUTHWEST. (NOTE: CANOPY STRUCTURE NEXT TO BUILDING FORMERLY COVERED GAS PUMPS; CANOPY BUILT IN 1930s BUT MOVED TO THIS LOCATION IN ABOUT 1970.)
- OR-160-E-2 VIEW OF WEST SIDE AND SOUTH FRONT OF BUILDING #2500, FACING NORTHEAST.
- OR-160-E-3 INTERIOR VIEW OF BUILDING #2500, FACING NORTHWEST.

Note: All photographs are 8" x 10" enlargements from 4" x 5" negatives.